


100  
AVE

29

- 1. Entrance
- 2. Entrance Hall
- 3. Planter
- 4. Well
- 5. Living Room
- 6. Kitchen
- 7. Church
- 8. Chapel
- 9. Automobile Tunnel
- 10. Pedestrian Tunnel
- 11. Winery
- 12. Light Well
- 13. Stairs
- 14. Walkway
- 15. Patio
- 16. Sump Pit
- 17. Hothouse
- 18. Indoor Patio
- 19. Bedroom
- 20. Bedroom Court
- 21. Bathroom
- 22. Reading Room
- 23. Stairs to Lower Level
- 24. Tunnel Under
- 25. Glass Bottom Aquar
- 26. Nursery
- 27. Restaurant (incomp
- 28. Kitchen
- 29. Unopened

CORNELIA

100



100  
AVE

N. FORESTIERE

945

943

935

933

© **SEYMOUR ROSEN** 1975

photographer

1804 North Van Ness

Los Angeles, Calif. 90028

(213) 463-1629